

	<table border="1"> <tr><td>A</td><td>rebated part with welded corners</td></tr> <tr><td>B</td><td>sleeve part with welded corners</td></tr> <tr><td>C</td><td>screw 3,9 x 38</td></tr> <tr><td>D</td><td>screw 4,5 x 50</td></tr> <tr><td>E</td><td>rubber seal</td></tr> </table>	A	rebated part with welded corners	B	sleeve part with welded corners	C	screw 3,9 x 38	D	screw 4,5 x 50	E	rubber seal		
A	rebated part with welded corners												
B	sleeve part with welded corners												
C	screw 3,9 x 38												
D	screw 4,5 x 50												
E	rubber seal												
<p>1</p>			<p>2</p>										
	<p>3</p>	<p>4</p>											
<p>5</p>	<p>6</p>												
<p>7</p> <p>* hinge dependent</p>	<p>8</p>												